



SAFETY FLASH

BU:	Deutschland	Plant:	Herrath
Activity:	CIP	Date:	18.03.2022
Place of accident:	Production	Contact:	J.Rippegarten

1. Beschreibung der Situation

Until now, the cleaning caustic solutions were stored via conventional IBC containers. The disadvantage of this was that there was always a large residual quantity in the container that had to be rinsed out and the suction lance that always had to be assembled and disassembled by hand. This creates a high risk of the lye splashing during disassembly. These containers have now been replaced with Varioboxes in the first steps. This has the advantage that the suction lances are located inside and can be mounted and dismantled much more safely via a Safeline connection. In addition, there is a much smaller residual quantity in the container, which no longer needs to be cleaned.



This is a great development for health promotion and serves to prevent accidents.

Keep it up!

